Chemistry Microbiology, and Technical Services

CLIENT: Alaskan Copper Works

628 S. Hanford Seattle, WA 98134

ATTN : Dale Olsen

Work ID : Client Taken By

Transported by: Hand Delivered : Sand Blast Type

SAMPLE IDENTIFICATION:

Sample

Description

3200 Sand Blast

The flag "U" indicates the analyte of interest was not detected, to the limit of detection shown.

Unless otherwise instructed all samples will be discarded on 08/05/90

Respectfully submitted, Laucks Testing Laboratories, Inc.

Certificate of Analysis

Work Order# : 90-06-171

DATE RECEIVED : 06/07/90

DATE OF REPORT: 06/29/90 CLIENT JOB ID : M15276



This report is submitted for the exclusive use of the person, partnership, or corporation to whom it is addressed. Subsequent use of the name of this company or any member of its staff in connection with the advertising or sale of any product or process will be granted only on contract. This company accepts no responsibility except for the due performance of inspection and/or analysis in good faith and according to the rules of the trade and of science.